

Heavy Metals Total Decomposition	Measurement	Detection Limit	Unit
As	< 1	1	Mg/Kg
Ba	< 1	1	Mg/Kg
Be	< 1	1	Mg/Kg
Cd	< 0.2	0.2	Mg/kg

Heavy Metals	Measurement	Detection Limit	Unit
Co	< 1	1	Mg/Kg
Cr	< 1	1	Mg/Kg
Cu	1950	1	Mg/Kg
Hg	< 0.2	0.2	Mg/Kg

Heavy Metals	Measurement	Detection Limit	Unit
Mo	< 1	1	Mg/Kg
Ni	< 1	1	Mg/Kg
Pb	< 1	1	Mg/Kg
Sb	< 1	1	Mg/Kg

Heavy Metals	Measurement	Detection Limit	Unit
Se	< 5	5	Mg/Kg
Sn	< 1	1	Mg/Kg
Te	< 2	2	Mg/Kg
U	< 1	1	Mg/Kg

Heavy Metals	Measurement	Detection Limit	Unit
V	< 1	1	Mg/Kg
Zn	< 1	1	Mg/Kg
Keine Daten	Keine Daten	Keine Daten	Keine Daten
Keine Daten	Keine Daten	Keine Daten	Keine Daten